rom :

Vemorandum

Bob Middleton, Chief Compliance Monitoring Unit Division of Operations and Maintenance

Wayne Gentry, Chief
Data and Flood Control Planning Branch
Central District
Department of Water Resources



Date : FED 20 1335

File No.:

Subject: Summary of Water Quality Monitoring During 1984 Old River Closure

The combined effects of seasonal low flows and Federal and State water project operations sometimes create flow reversals and low dissolved oxygen problems in the San Joaquin River system. To minimize the detrimental effects of these adverse conditions near Stockton, the Department installs a rock barrier at the head of Old River upon request by the Department of Fish and Game. This usually occurs when flows at Vernalis fall below 500 cubic feet per second. This control structure effectively forces a greater portion of the San Joaquin River flow downstream past Stockton, instead of allowing it to be diverted down Old River to the export pumps. The greater flow flushes out the "pollution block" that forms in the deep ship channel and creates a net downstream flow for migrating salmon. Placement of the closure and associated water quality monitoring are part of an effort to restore depleted fall salmon runs in this area.

In 1984, the closure was completed on September 8 and removed on October 19. Attached is a summary of water quality monitoring on September 4 and October 5 to determine effectiveness of the control structure.

Attachment

cc: Jim Snow

A. Prosta 2/25 11 4/2 ty 2/25

SURNAME

SUMMARY OF WATER QUALITY MONITORING DURING 1984 OLD RIVER CLOSURE

In 1984, guidelines for installation of the rock barrier across Old River at its juncture with the San Joaquin River were taken from the pending Two-Agency Fish Agreement between the Department of Water Resources (DWR) and the Department of Fish and Game (DFG). The criterion specified in that agreement is to provide a minimum net downstream flow of 500 cfs in the San Joaquin River past Stockton. According to the Sacramento Valley Four Basin Index defined in Water Right Decision 1485, water year 1984 was classified as wet, with modification for subnormal snowmelt.

Responsibility for implementing the water quality monitoring in 1984 was assigned to the D-1485 Monitoring and Analysis Section, Central District. Program management remained with the Division of Operation and Maintenance. Water quality data gathered by DWR were periodically reviewed by DFG to determine if further measures would be necessary to improve conditions for migrating salmon.

The closure was started on September 5 and completed on September 8. DFG had requested that the barrier remain in place until November 30 so that late migrants could benefit from the increased net flows. However, the closure had to be removed on October 19, when the right levee embankment adjacent to the barrier began to erode, causing a 90- by 30-foot hole. DFG concurred in removal of the closure at that time because unseasonably low temperatures and excessive rains, coupled with higher outflows, had improved water quality. conditions in the Stockton Deep Water Ship Channel.

The area monitored in 1984 was from Prisoner's Point, on the San Joaquin River, to the Deep Water Ship Channel turning basin near Stockton (see Figure I). To increase sampling accuracy and efficiency in 1984, the D-1485 Monitoring Section used a land-based continuous monitoring station on Rough and Ready Island, which has telemetry capabilities. Real-time dissolved oxygen (DO) readings were made available for use by DWR and DFG upon interrogation from Sacramento. The land-based station allowed DWR to schedule special DO runs from a remote location based on actual water quality conditions, as opposed to random runs with the research vessel San Carlos, to ensure criteria were being met. This resulted in an estimated savings of \$4,500.

On September 4 and October 5, the San Carlos was used to collect samples at depths of 1 meter below the water surface and 1 meter off the channel bottom at 12 sites during the morning ebb slack tide. Discrete measurements included DO, electrical conductivity (EC), air and water temperature, and depth of channel. Continuous parameter profiles were charted for DO, turbidity, in-vivo chlorophyll, pH, EC, and water temperature. Results are shown in Table 1.

The September run provided a base condition to compare water quality changes resulting from installation of the barrier. At that time a classic DO sag was measured in the ship channel between Light 12 and Light 34 (see Figure 2). The sag actually extended into the turning basin, but was interrupted by higher DO water entering the channel from the upper San Joaquin at Light 48. This caused DO values to increase from Light 34 to Light 48, with a noticeable peak at Light 48. The elevated value in the turning basin was the result of a dense,

highly visible algal bloom (described as a "green soup"). This enhanced algal activity results in highly oxygenated water due to photosynthetic action. Typically, the bottom DO is depressed, with a sharp saturation interface at the euphotic zone boundary (extent of available light for photosynthesis). The entire water column becomes deficient in DO during non-daylight hours.

Dissoved oxygen levels of 5.0 mg/L or more are believed to be necessary to encourage fish to migrate through the ship channel into the upper San Joaquin River to spawn. The post-closure survey on October 5 showed that DO levels were all above 6.9 mg/L, except for the bottom measurement in the turning basin (see Figure 3). This lower value of 6.4 was probably due to organic material from the earlier algal bloom settling to the bottom, creating a biological oxygen demand.

The pre- and post-closure runs both reflect the reverse salinity gradient usually formed by the high volume of agricultural waste water being discharged into the system. The higher EC water was transported down the San Joaquin River and, after entering the ship channel, mixed with lower EC water originating downstream.

DWR and DFG considered a third run to measure any adverse consequences at the time the barrier "washed out". However, based on data from the Rough and Ready Island station, it was deemed unnecessary. Average hourly DO readings from that land-based station from the time of closure through November never dropped below 5.0 ppm.

In addition to the water quality monitoring, water flow was measured down the San Joaquin River and Old River after the rock barrier was installed. Although the quantity of flow involved is important, the main objective is to maintain a net downstream flow pattern, which provides "homing" water for migrating salmon. After the barrier was installed, flows down both the San Joaquin River and Old River were positive (downstream): 2,237 cfs down the San Joaquin and 803 cfs down Old River.

Table 1
STOCKTON DISSOLVED OXYGEN STUDY FIELD DATA — 1984

	, · · · · · · · · · · · · · · · · · · ·							
	09/04/84				10/05/84			
Station	DO (mg/L)	EC (uS/cm)	Water (°C)	Air (°C)	DO (mg/L)	EC (uS/cm)	Water (°C)	Air (°C)
Light 6	7.7 7.8	214 205	23 23	24	7.6 7.7	306 302	20 20	17
Light 12	7.3 7.3	239 232	24 23	24	6.9 7.2	383 370	20 20	19
Light 14	6.7 6.7	366 345	24 24	25	6.9 6.9	424 423	20 20	20
Light 18	6.1 6.2	584 410	24 24	26	7.0 6.9	415 417	20 20	22
Light 19	5.8 5.6	498 512	24 24	26	7.1 7.0	411 416	20 20	22
Light 28	5.4 5.2	533 546	25 24	28	7.3 7.2	408 409	20 20	22
Light 34	5.3 5.0	539 456	24 24	28	7.1 7.4	413 406	20 20	24
P8	6.2 5.3	548 550	25 24	29	8.3 7.6	400 407	21 20	23
Light 41	6.4 5.7	522 541	25 24	32	7.9 7.8	400 419	20 20	23
Light 43	6.8 5.4	548 541	24 24	34	8.1 7.8	417 411	20 20	23
Light 48	6.6 6.1	498 450	24 24	35	7.9 7.8	392 387	20 20	24
Turning Basin	9.4 4.6	600 528	25 24	35	7.8 6.4	480 427	21 20	25

First value = 1 meter below water surface.
Second value = 1 meter above channel bottom.





